RH\$PETERSON co. Technical Services Bulletin 17-03

Older D1 Log Sets Should Not Be Used with New DVI Model Inserts

Contrary to earlier advice, the following D1 log sets should not be used with the new Real Fyre DVI direct vent gas inserts:

| Model No. | Description |
|-----------|---|
| D1-25-2A | Burnt American Oak Gas Logs (25") |
| D1-25-2S | Split Burnt American Oak Gas Logs (25") |
| D1-30-2A | Burnt American Oak Gas Logs (30") |
| D1-30-2S | Split Burnt American Oak Gas Logs (30") |
| D1-36-2A | Burnt American Oak Gas Logs (36") |
| D1-36-2S | Split Burnt American Oak Gas Logs (36") |

While not a safety issue, using these logs in the new models can result in unsatisfactory flame performance. The D1 log sets may of course be used with the older D1 gas inserts.

Given the potential for confusion, if you only have new DVI inserts in inventory it is recommended that you contact your RH Peterson sales representative to arrange for replacement of all old D1 log sets with new DVI versions.

We regret the inconvenience and appreciate your cooperation.